Attorney Docket No.: 02SPE130P Patent No. 6,984,577

Serial No. 09/665,422

COFC



## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant(s): **Zhao, et al.** Patent No.: **6,984,577** 

Issue Date: January 10, 2006 Filing Date: September 20, 2000

Application Serial No.: 09/665,422

Title: Damascene Interconnect Structure

and Fabrication Method Having Air

Gaps Between Metal Lines and

Metal Layers

Group Art Unit: 2815

Examiner: Diaz, Jose R.

## REQUEST FOR A CERTIFICATE OF CORRECTION FOR PTO'S ERROR

Commissioner for Patents
Office of Patent Publication
Attention: Certificate of Correction Branch
P.O. Box 1450
Alexandria, VA 22313-1450

MAY 2 2 2005

Dear Sir/Madam:

Applicants respectfully request that a certificate of correction be issued to correct a clerical error made by the Patent Office in the claims of the above-referenced patent, and no fault of applicant, as shown in the enclosed copy of Form PTO-1050.

The Assistant Commissioner is hereby authorized to charge or credit Deposit Account No. 50-0731 for any deficiency or overpayment in the fees required for the filing of this request for a certificate of correction, for which purpose a duplicate copy of this paper is also included.

PEGEIVED-USPTO

MAY 2 3 2008

Attorney Docket No.: 02SPE130P Patent No. 6,984,577 Serial No. 09/665,422

A certificate of correction is respectfully requested. Applicants respectfully invite the examiner to contact the undersigned for any questions.

Respectfully Submitted; FARJAMI & FARJAMI LLP

Michael Farjami, Esq.

Reg. No. 38,135

Date: 5/15/08

. [

Michael Farjami, Esq. FARJAMI & FARJAMI LLP 26522 La Alameda Ave., Suite 360 Mission Viejo, California 92691

Tel: (949) 282-1000 Fax: (949) 282-1002

**CERTIFICATE OF MAILING** 

Christina Carter

THORN TO USPTO

MAY 2 3 2008



Attorney Docket No.: 02SPE130P Patent No. 6,984,577 Serial No. 09/665,422

# IN THE UNITED STATES PATER PARTY TRADEMARK OFFICE

Applicant(s): Zhao, et al.

Patent No.: 6,984,577

Issue Date: January 10, 2006
Filing Date: September 20, 2000
Application Serial No.: 09/665,422

Title: Damascene Interconnect Structure

and Fabrication Method Having Air

Gaps Between Metal Lines and

**Metal Layers** 

Group Art Unit: 2815

Examiner: Diaz, Jose R.

# REQUEST FOR A CERTIFICATE OF CORRECTION FOR PTO'S ERROR

Commissioner for Patents Office of Patent Publication Attention: Certificate of Correction Branch P.O. Box 1450 Alexandria, VA 22313-1450

#### Dear Sir/Madam:

Applicants respectfully request that a certificate of correction be issued to correct a clerical error made by the Patent Office in the claims of the above-referenced patent, and no fault of applicant, as shown in the enclosed copy of Form PTO-1050.

The Assistant Commissioner is hereby authorized to charge or credit Deposit Account No. 50-0731 for any deficiency or overpayment in the fees required for the filing of this request for a certificate of correction, for which purpose a duplicate copy of this paper is also included.

PLOSIVED NOPTO

MAY 2 3 2008

Attorney Docket No.: 02SPE130P Patent No. 6,984,577 Serial No. 09/665,422

A certificate of correction is respectfully requested. Applicants respectfully invite the examiner to contact the undersigned for any questions.

Respectfully Submitted; FARJAMI & FARJAMI LLP

Date:  $\frac{5/15/08}{}$ 

Michael Farjami, Esq. Reg. No. 38,135

Michael Farjami, Esq. FARJAMI & FARJAMI LLP 26522 La Alameda Ave., Suite 360 Mission Viejo, California 92691

Tel: (949) 282-1000 Fax: (949) 282-1002 CERTIFICATE OF MAILING

Unistina Carter

REGENTED MISPITO Floor Politication U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,984,577

Page \_1\_ of \_1\_

APPLICATION NO.

: 09/665,422

**ISSUE DATE** 

: 1/10/2006

INVENTOR(S)

: Zhao, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the claims, column 12, line 28, "spaced-apart-metal lines" should be changed to --spaced-apart metal lines--.

### MAILING ADDRESS OF SENDER:

Michael Farjami, Esq. Farjami & Farjami LLP 26522 La Alameda Avenue, Suite 360 Mission Viejo, California 92691

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner, for Ratents; P.O. Box 1450, Alexandria, VA 22313-1450.